





Technical information
Explosion drawing and parts list

AB111N (7900100) JOINTING MACHINE AB111N (OLD) | Version A

| Pos. | Serial No. | Code | Description | Quantity |
|------|------------|---------|--|----------|
| 1 | | 1204003 | BEARING HOLDER | 1 |
| 2 | | 1210019 | BALL BEARING 607 Z | 1 |
| 3 | | 1323049 | RETAINER | 1 |
| 4 | | 1323077 | WRENCH | 1 |
| 5 | | 1323078 | WASHER E=0.2 | 1 |
| 5 | | 1323079 | WASHER E=0.1 | 1 |
| 6 | | 1402083 | HANDLE | 1 |
| 7 | | 1402099 | STOPPER CONTROL | 1 |
| 8 | | 1403055 | WASHER | 1 |
| 9 | | 1416095 | LABEL | 2 |
| 10 | | 1422086 | BLADE HOLDER | 1 |
| 11 | | 1422087 | BLADE FLANGE | 1 |
| 12 | | 9999998 | CHANGED SPARE PART POSITION | 1 |
| 13 | | 9999998 | CHANGED SPARE PART POSITION | 1 |
| 14 | | 1423086 | WRENCH | 1 |
| 15 | | 1426032 | SPRING | 2 |
| 16 | | 1426034 | SPRING | 1 |
| 17 | | 1426051 | SPRING | 2 |
| 18 | | 1428029 | NUT | 1 |
| 19 | | 1440080 | CARBIDE BLADE D.100X4 | 1 |
| 19 | | 1440382 | BIT D.100X4 | 1 |
| 20 | | 1473013 | FLAT HD. SCREW M.5X8 PH. | 1 |
| 21 | | 1475027 | HEX. SOCKET HD. CAP SCREW M.10X15 | 2 |
| 22 | | 1488028 | RETAINING RING D.3.2 | 1 |
| 23 | | 1499031 | SCREWDRIVER | 1 |
| 24 | | 1499032 | OIL POT | 1 |
| 25 | | 2015043 | SWITCH | 1 |
| 26 | | 2045292 | SET BRUSH HOLDER W/CARBON BRUSHES 230V | 1 |
| 26 | | 2045703 | SET BRUSH HOLDER W/CARBON BRUSHES 120V | 1 |
| 27 | | 3504030 | RUBBER PIN | 2 |
| 28 | | 4302025 | CORD CLAMP | 1 |
| 29 | | 4383009 | WASHER D.10.5 | 2 |
| 30 | | 4410021 | BALL BEARING 629-ZZ | 1 |
| 31 | | 4610022 | BALL BEARING 6201-2RS | 1 |
| 32 | | 4679013 | SCREW D.4X25 TX | 2 |
| 33 | | 1400051 | CORD ASS'Y (AMERICA) | 1 |
| 33 | | 5400025 | CORD ASS'Y (EUROPE) | 1 |
| 34 | | 6403028 | END COVER | 1 |
| 35 | | 6403029 | NOZZLE | 1 |
| 36 | | 6403030 | REGULATION STOPPER GAGE | 1 |
| 37 | | 6404053 | RUBBER | 2 |
| 38 | | 6407032 | FIXED FRONT PART | 1 |
| 39 | | 6429011 | STOPPER | 1 |
| 40 | | 6429013 | LEFT RING | 1 |
| 41 | | 6429028 | RIGHT RING | 1 |
| 42 | | 6446092 | FENCE ASS'Y | 1 |
| 43 | | 6477012 | RIGHT SCREW | 1 |
| 44 | | 6477013 | LEFT SCREW | 1 |



Technical information
Explosion drawing and parts list

AB111N (7900100) JOINTING MACHINE AB111N (OLD) | Version A

| | | | |
|----|---------|----------------------------------|---|
| 45 | 6478001 | SCREW M.4X8 PH. | 4 |
| 46 | 6478002 | SCREW M.4X12 PH. | 4 |
| 47 | 6673010 | FLAT HD. SCREW M.5X8 PH. | 1 |
| 48 | 7080059 | WASHER D.9.1X22X0.2 | 1 |
| 49 | 7903071 | FAN GUIDE | 1 |
| 50 | 7906144 | SLIDE | 1 |
| 51 | 7906145 | BASE | 1 |
| 52 | 7906340 | BEARING COVER | 1 |
| 53 | 7907063 | GEAR HOUSING | 1 |
| 54 | 7912028 | SELF LUBRICATED BEARING A8X12X10 | 1 |
| 55 | 7919318 | LABEL | 1 |
| 56 | 7920053 | GEAR SPINDLE | 1 |
| 57 | 7929026 | NUT M.6 | 1 |
| 58 | 7929027 | NUT M.9 | 1 |
| 59 | 7945606 | ELECTRONIC CIRCUIT | 1 |
| 59 | 7945667 | ELECTRONIC CIRCUIT ASS'Y 120 V. | 1 |
| 60 | 7950095 | GEARS SET (MG10) | 1 |
| 61 | 7951168 | ARMATURE ASS'Y 230 V. | 1 |
| 61 | 7951171 | ARMATURE ASS'Y 120 V. | 1 |
| 62 | 7978004 | SCREW M.4X25 PH. | 4 |
| 63 | 8002043 | CORD ARMOR | 1 |
| 64 | 8678008 | SCREW M.4X10 PH. | 3 |
| 65 | 9202451 | COVER | 1 |
| 66 | 9202453 | RIGHT COVER | 1 |
| 67 | 9202454 | LEFT COVER | 1 |
| 68 | 9202455 | TIE ROD | 1 |
| 69 | 7902835 | MOTOR HOUSING | 1 |
| 70 | 9202458 | PUSH BUTTON | 1 |
| 71 | 9217035 | CARBON BRUSHES SET | 1 |
| 71 | 9217041 | CARBON BRUSHES 120 V. | 1 |
| 72 | 9226155 | BRUSH SPRING | 2 |
| 75 | 9255162 | STATOR ASS'Y 230 V. | 1 |
| 75 | 9255165 | STATOR ASS'Y 120 V. | 1 |
| 76 | 9268299 | CAPACITOR | 1 |
| 77 | 9279018 | SCREW D.4X40 (TX) | 7 |
| 79 | 9999998 | CHANGED SPARE PART POSITION | 2 |
| 80 | 6019390 | LABEL | 1 |